



HANLON WINDOWS

Glass Cleaning and Maintenance

This information is offered as general information only. Specific advice on the cleaning of glass should always be sought from a reputable glazier or professional window cleaner before any glass cleaning is undertaken.

How to clean glass with a Low E coating?

- Make sure to remove any jewellery that may scratch the surface of the glass.
- Spray on a clear liquid window cleaner, such as clear Windex or a mixture of 1 part vinegar to ten parts water (no coloured liquids)
- Use a lint free cloth to wipe over window
- To prevent streaking, stop wiping when the glass is almost dry and there is a uniform residue of moisture left on the glass surface. The residue will quickly evaporate leaving a clean surface.

How to clean standard glass, toughened glass and most double glazing?

- Use the same steps as above. This method can be used for all glass to avoid damage to the window.

Spot Cleaning:

- Make sure to remove any jewellery that may scratch the surface of the glass.
- Apply a small quantity of Methylated Spirits to a clean, wet cloth or towel. (Please use strictly in accordance with manufacturer's recommendations and warnings)
- Rub on areas of glass needing spot cleaning.
- Wipe clean using a dry, clean, lint free towel or cloth followed by a routine cleaning procedure.